WA-I- 521 Frame Farmhouse

Late 19th century

Hagerstown Vicinity

Private

The Frame Farmhouse is a two-story, five-bay by three-bay structure covered in aluminum siding. It has a gable roof with a large gable dormer. The main facade has a central entrance with windows in the other four bays on the first story and five bays on the second story. There is a small square window in the front dormer. The house has an L-shaped plan.

TYPE-ERASE

25% CONTON FIRENUS A

Maryland Historical Trust
State Historic Sites Inventory Form

Magi No.

DOE __yes __no

1. Name (indicate pr	referred name)		
historic frame farmhouse		1, 1, 1	
and/or common			
2. Location	() H		= >
street & number east side of Rt.	65, .5 mile south of	I-70 _	not for publication
city, town	X_ vicinity of	town congressional district	sixth
state Maryland	county	Washington	
3. Classification	П	,	
Category Ownership districtpublicbuilding(s)privatebothsite	Status occupied unoccupied work in progress Accessible yes: restricted yes; unrestricted no	Present Useagriculturecommercialeducationalentertainmentgovernmentindustrialmilitary	museum park private residence religious scientific transportation other:
4. Owner of Prope	rty (give names an	d mailing addresses	s of <u>all</u> owners)
street & number		telephone no	.:
city, town	state	and zip code	
5. Location of Leg	al Descriptio	n	
courthouse, registry of deeds, etc. Wa	shington County Cour	thouse	liber 561
street & number Washington Street			folio 567
city, town Hagerstown		state	Maryland
6. Representation	in Existing	Historical Surve	eys
title			
date		federal state	countyloca
depository for survey records			
city, town		state	

Condition		Check one	Check one	
excellent good fair	deteriorated ruins unexposed	unaltered altered	original site moved date of move	

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The frame farmhouse is a two-story, five-bay by three-bay structure covered in aluminum siding. It has a gable roof with a large gable dormer. The main facade has a central entrance with windows in the other four bays on the first story and five bays on the second story. There is a small square window in the front dormer. The house has an L-shaped plan. It appears to have been constructed in the late 19th century.

The frame farmhouse is located on the east side of Rt. 65, .5 mile south of I-70. It sits on a small rise just off the main highway in the vicinity of two earlier farmsteads.

The farmhouse currently has a modern aluminum siding on the exterior. It also has modern exterior concrete block flue is on the northernmost gable end of the building. The gable roof is covered in asphalt shingles. The windows throughout the house are one-over-one pane sash windows. The only ornamentation on the house is the turned posts on the full-length, one-story porch.

The property contains no significant outbuildings, but does contain several small buildings including a garage and shed.

Prepare both a summary paragraph of significance and a general statement of history and support.

Based on the MHT Survey Matrix, this is a mid-level site. It is a representative late 19th century farmhouse for this region. Its architectural intregrity has been diminished by application of modern siding and removal of period ornamentation.

9. Major Bibliographical References

Survey No. WA-I-501 521

selven se	ariq . Teaming	The work old force	271		in the same	Mr. It - Mr.
Acreage of nominated property		Yuselen		trating in	over a series	
Quadrangle name				Quadrang	le scale	
UTM References do NOT complet	te UTM refer	rences				
Zone Easting Northin	ng .	B	Easti	ng	Northing	لبيا
	لبيار	DL	LL	لبيل	ليليا	
ELI LILII LI		FLL	LL		LILI	11
$G \cup I \cup I \cup I \cup I$	البياء	HLL	11	IIII	Lilil	11
List all states and counties for pr	operties over	lapping state or c	ounty	ooundaries		9
	operties over	lapping state or c	ounty	ooundaries	code	
List all states and counties for pr state state	Contract Store	A STATE OF THE PARTY OF THE PAR	ounty	ooundaries		A
state	code	county	ounty	ooundaries	code	
state state 11. Form Prepar	code	county	ounty	boundaries	code	
state 11. Form Preparename/title Joe Getty	code code ed By	county	ounty	May 1983	code	
state 11. Form Preparename/title Joe Getty	code code ed By	county	e de	May 1983	code	

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust


Shaw House

21 State Circle

Annapolis, Maryland 21401

(301) 269-2438

WA-I-521 Frame Farmhouse 10319 Sharpsburg Pike (MD 65) Funkstown Quadrangle



1993-94 Aerial Photo



Tax Map 57, p. 160





- 1. Frame Farmhouse WA-I-501 52/
- 2. Washington County, Maryland
- 3. Joe Getty
- 4. May 1983
- 5. Maryland Hist. Trust, Annapolis, Md.
- 6. West facade; camera facing east
- 7. 1/1